

Inspection Photos and Issue Report

9/7/2022

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location #335961

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #335961



September 7, 2022



September 7, 2022

Photo 1: Photos taken from the west of the working pad. Photos 1-2 provide an overview of the production areas from north, northeast, southeast to south.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #335961



September 7, 2022



September 7, 2022

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #335961



Photo 3: Active wells on Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #335961



Photo 4: Tank battery facility

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #335961



Photo 5: Photo shows unused production equipment stored within the secondary containment berm of the tank battery.



Photo 6: Photo shows unused pipe equipment stored within the secondary containment berm of the tank battery.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #335961



September 7, 2022



September 7, 2022

Photo 7: Photos examples showing interim areas of the Location; interim reclamation “in process” and appears to be progressing towards 1003 standards.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #335961



Photo 8: Tank label w/ incorrect Operator name