

Inspection Photos  
103 10379

Inspection Date: 9/8/2022  
All Photos taken by Kris Neidel



Photo #1 sign at wellhead has not been updated to current operator.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos

103 10379

Inspection Date: 9/8/2022

All Photos taken by Kris Neidel



Photo #2 tank battery



Inspection Photos  
103 10379

Inspection Date: 9/8/2022  
All Photos taken by Kris Neidel



**Photo #3 partially buried tank is heaving and would allow fluid to the subsurface in case of a spill.**



Inspection Photos

103 10379

Inspection Date: 9/8/2022

All Photos taken by Kris Neidel



**Photo #4 partially buried tank is heaving and would allow fluid to the subsurface in case of a spill. It appears that the tank is not piped, if tank is not necessary, it should be removed.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources