

Inspection Photos
Location Name: Becker Ranch 5RU-TB Pad
Facility ID: 481807




Photo #1 Location



Photo #2 Removed Stained Soil

Inspection Photos
Location Name: Becker Ranch 5RU-TB Pad
Facility ID: 481807



Photo #3 Removed Stained Soil

Photo #4 Removed Stained Soil