



**Inspected Facilities**

Facility ID: 272460 Type: WELL API Number: 071-08078 Status: AC Insp. Status: AC

**Cement**

Cement Contractor

Contractor Name: \_\_\_\_\_

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 320

Cement Volume (sx): 43

Good Return During Job: YES

Cement Type: NEAT G

Comment: SET TBG @ 320' PUMPED 43 SKS NEAT G CEMENT AND CIRCULATED TO METAL WORKING PIT.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695106712	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5857382">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5857382</a>