

Final Reclamation and Stormwater Inspection

Date: 09/08/2022

Operator: SCHNEIDER ENERGY SERVICES INC - 313839

Location ID: 313839

Inspection Document #: 696105418

Morgan County, CO

NENE Section 31 T5N R59W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STROMSOE 1
Location ID: 313839



Photo 1. Access road photo taken from county road, facing southeast. Photo illustrates access road has not been reclaimed with presence of bare soil.

Inspection Photos
Location Name: STROMSOE 1
Location ID: 313839



Photo 2. See comments in photo 1.

Inspection Photos
Location Name: STROMSOE 1
Location ID: 313839



Photo 3. Location photo taken from center portion, facing north. Photo illustrates lack of uniform vegetation cover resulting in bare soil.

Inspection Photos
Location Name: STROMSOE 1
Location ID: 313839



Photo 4. Facing west, see comments in photo 3.

Inspection Photos
Location Name: STROMSOE 1
Location ID: 313839



Photo 5. Facing south, see comments in photo 3.

Inspection Photos
Location Name: STROMSOE 1
Location ID: 313839



Photo 6. Photo taken from western portion, facing southeast. Photo illustrates reclaimed area has stunted vegetation and is not reflective of reference area crop.

Inspection Photos
Location Name: STROMSOE 1
Location ID: 313839



Photo 7. Facing north, see comments in photo 6.

Inspection Photos
Location Name: STROMSOE 1
Location ID: 313839



Photo 8. Reference area photo taken from northeastern portion of location, facing east.