

Inspection Photos
Location: GR 32-34-696 Production Facility
Location ID: 324068
Spill/Release ID: 482475
Inspection Date: July 25, 2022

Location sign.



Inspection Photos
Location: GR 32-34-696 Production Facility
Location ID: 324068
Spill/Release ID: 482475
Inspection Date: July 25, 2022

80 bbl Produced Water steel AST
on location adjacent to the
spill/release area.



Inspection Photos

Location: GR 32-34-696 Production Facility

Location ID: 324068

Spill/Release ID: 482475

Inspection Date: July 25, 2022

Spill/release area as seen from the
GR 32-34-696 Production Facility
location looking south.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location: GR 32-34-696 Production Facility

Location ID: 324068

Spill/Release ID: 482475

Inspection Date: July 25, 2022

Spill/release area looking towards
the GR 32-34-696 Production
Facility location and the 80 bbl
Produced Water steel AST.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources