

# Inspection Photos and Issue Report

9/12/2022

Operator: RIO MESA RESOURCES INC - 74740

Location #398346

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location #398346



**Photo 1:** Photo taken from the north end of the Location, facing south. Photo provides overview of the Location. Arrow shows areas of remaining pit and stockpile. Vegetation is not uniform and is predominantly Undesirable and Noxious Plant species.

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location #398346



**Photo 2:** Photo shows pit remaining on the southeast end of the Location.

## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location #398346



September 12, 2022



September 12, 2022

**Photo 3:** Photos example showing anchors remaining on the northwest and southwest ends of the Location. Anchor also observed on the southeast end of the location; unable to find northeastern anchor. Anchors require removal.

## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location #398346



**Photo 4:** Photos examples showing access road has not been recontoured/regraded and reclaimed.

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location #398346



**Photo 5:** Noxious weeds on Location.