

Inspection Photos
Location Name: Herrera Gas Unit A 4
Location ID: 326352



IMG 01
Well sign



IMG 02
Location overview



IMG 03

Lube oil has begun to impact material

IMG 04