

FIRR Photos
Inspection Doc # 696304258
Location Name: Livengood 7-7
Location ID: 327473



Photo 1 – Heater Treater & Tank Battery Areas with risers removed