

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4MWME

Location ID: 334850



Photo #7648 From entrance to location.



Photo #7649 From entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4MWME

Location ID: 334850



**Photo #7650 Multiple local lines open ended.**



**Photo #7651 Multiple local lines open ended.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4MWME

Location ID: 334850



**Photo #7652 Undesirable plant species in tank containment.**



**Photo #7653 Undesirable plant species in tank containment.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4MWME

Location ID: 334850



Photo #7654 Vent pipe on tank open ended.