

Interim Reclamation Inspection

September 13, 2022

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 480698

Inspection Document #: 697504172

Weld County, CO

NWSE Section 11 T1N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Martin J Schaefer #2 Flowline
Location ID: 480698



Photo 1. COGCC drone aerial imagery taken on September 13, 2022 documenting the scope of reclamation work to be performed. This image is the approximate extent of reclamation along the eastern project area.

Inspection Photos
Location Name: Martin J Schaefer #2 Flowline
Location ID: 480698



Photo 2. COGCC drone aerial imagery taken on September 13, 2022 documenting the scope of reclamation work to be performed. This image is the approximate extent of reclamation along the western and central project area.

Inspection Photos
Location Name: Martin J Schaefer #2 Flowline
Location ID: 480698



Photo 3. COGCC drone aerial imagery taken on September 13, 2022 documenting the scope of reclamation work to be performed. This image is the approximate extent of reclamation along the western project area.

Inspection Photos

Location Name: Martin J Schaefer #2 Flowline

Location ID: 480698



Photo 4. Photo taken from the eastern ditch, facing West. Photo illustrates native wetland vegetation has established within the ditch.



Photo 5. Photo taken from the central ditch, facing West. See comments under Photo 4.

Inspection Photos

Location Name: Martin J Schaefer #2 Flowline

Location ID: 480698



Photo 6. Photo taken from the western ditch, facing West. See comments under Photo 4.



Photo 7. Photo taken from the western fill slope, facing North. Photo illustrates erosion along the fill slope that needs to be repaired during reclamation. The erosion is believed to be from a recent irrigation event by the surface owner.