



SITE NAME: Moser Reigle 3C-4 HZ, 29C-9HZ O SA							DATE: 9/7/2022	REM. PROJECT #:	WEATHER: Sunny, 90 F		
SITE DIRECTIONS: Cr 41 & Cr 24, N 0.4, E 0.4 into							CLIENT: Oxy				
LEGALS AND LAT/LONG: 40.1681249,-104.6689109							TASMAN PERSONNEL: Patrick Downs				
SOIL TYPES: Well Graded Sand - SW							SURFACE GRADIENT: East				
SOIL SAMPLING							FACILITY INFRASTRUCTURE				
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity		
							Above Ground Storage Tank (AST)		8		
9/7/2022 09:30	AST1-B01@3"	0.0	No Staining	No Odor	Yes	N/A	Buried or Partially Buried Vessel				
9/7/2022 09:32	AST1-B02@3"	0.1	No Staining	No Odor	Yes	Lab	Separator				
9/7/2022 09:34	AST2-B01@3"	0.2	No Staining	No Odor	Yes	N/A	Emission Control Device (ECD)		3		
9/7/2022 09:36	AST2-B02@3"	0.2	No Staining	No Odor	Yes	Lab	Dump Line				
9/7/2022 09:38	AST3-B01@3"	0.0	No Staining	No Odor	Yes	N/A	Wellhead				
9/7/2022 09:40	AST3-B02@3"	0.2	No Staining	No Odor	Yes	Lab	Flowline				
9/7/2022 09:42	AST4-B01@3"	0.1	No Staining	No Odor	Yes	N/A	Other:				
9/7/2022 09:44	AST4-B02@3"	0.1	No Staining	No Odor	Yes	Lab	Soil Loads Removed				
9/7/2022 09:46	AST5-B01@3"	0.1	No Staining	No Odor	Yes	N/A	IMPACTED SOIL IDENTIFIED?				
9/7/2022 09:48	AST5-B02@3"	0.2	No Staining	No Odor	Yes	Lab	ESTIMATED VOLUME OF IMPACTS:				
9/7/2022 09:50	AST6-B01@3"	0.2	No Staining	No Odor	Yes	Lab	Date		Number		CY
9/7/2022 09:52	AST6-B02@3"	0.1	No Staining	No Odor	Yes	N/A					
9/7/2022 09:54	AST7-B01@3"	0.1	No Staining	No Odor	Yes	N/A					
9/7/2022 09:56	AST7-B02@3"	0.1	No Staining	No Odor	Yes	Lab					
9/7/2022 09:58	AST8-B01@3"	0.2	No Staining	No Odor	Yes	N/A					
9/7/2022 10:00	AST8-B02@3"	0.2	No Staining	No Odor	Yes	Lab	Total Removed		0		0
9/7/2022 10:02	ECD-B01@3"	0.0	No Staining	No Odor	Yes	N/A	Disposal Facility:				
9/7/2022 10:04	ECD-B02@3"	0.4	No Staining	No Odor	Yes	N/A	Groundwater Recovery				
9/7/2022 10:06	ECD-B03@3"	0.1	No Staining	No Odor	Yes	N/A	DATE GW ENCOUNTERED:			DEPTH:	
9/7/2022 10:08	BG-01@3"	0.0	No Staining	No Odor	Yes	Lab	GROUNDWATER IN CONTACT WITH IMPACTED SOIL?				
9/7/2022 10:10	BG-02@3"	0.0	No Staining	No Odor	Yes	Lab					
9/7/2022 10:12	BG-03@3"	0.3	No Staining	No Odor	Yes	Lab	LNAPL OR SHEEN OBSERVED ON GW?				
GROUNDWATER SAMPLING							Date		BBLs		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?					
							Total Removed		0		
							Disposal Facility:				

Photographic Log



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Photographic Log




Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Photographic Log


Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Photographic Log


Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Photographic Log


Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			



Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log



Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:		Volume:		Material:		Volume:	
Contents:			Contents:				
Notes/Conditions:				Notes/Conditions:			