

Inspection Photos and Issue Report

9/16/2022

Operator: CAERUS PICEANCE LLC - 10456

Location #312482

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #312482



September 15, 2022



September 15, 2022

Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide overview of the Location from west, northwest, northeast to east. Location has met 1004 standards.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #312482



September 15, 2022



September 15, 2022

Photo 2: See comments under photo 1.