

Inspection Photos and Issue Report

9/15/2022

Operator: CAERUS PICEANCE LLC - 10456

Location #312401

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #312401



Photo 1: Photos 1-4 provide a 360 degree overview of the Location. Location has met 1004 revegetation standards.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #312401



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #312401



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #312401



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #312401



Photo 5: Photo taken from the west end of the Location. Photo shows two tamarisk plants established on the Location.

