

Inspection Photos and Issue Report

9/15/2022

Operator: CAERUS PICEANCE LLC - 10456

Location #312659

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #312659



September 15, 2022



September 15, 2022

Photo 1: Photos provide overview of the Location. Location has met 1004 revegetation standards.