


**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Weeds at well and pump jack.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Junk at well head.**



**Junk at well head.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Propane tank with no labeling.**



**Propane tank with no labeling.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**5 gallon bucket of oil with no lid or secondary containment.**



**5 gallon bucket of oil with no lid or secondary containment.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Oil stained ground at well.**



**Oil stained ground at pumpjack engine.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Heated separator. Weeds in berm.**



**Stained ground at separator.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Stained ground at separator.**



**Stained ground at separator.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**2 - 55 gallon drums with no labels and no secondary containment at separator.**



**Open drum at separator.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Incorrect capacity on tank label.**

**Tank battery on well site location. Weeds in berm.  
Latitude: 40.489754 Longitude: -107.11463**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Stained ground at tank valve. Weeds in berm.**



**Stained ground at tank. Leaks from bolted on cover.  
Weeds in berm.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Tank battery Weeds**

**Latitude: 40.487835 Longitude: -107.116073**

**Tank battery Weeds**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Oil stained ground inside of tank berm.**



**Oil stained ground inside of tank berm.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Tanks have painted on graffiti.**



**Tanks have painted on graffiti. Label is painted over.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Tanks have painted on graffiti.**



**Tanks have painted on graffiti. Label is painted over.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Oil stained ground inside of tank berm.**



**Oil stained ground inside of tank berm.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Oil stained ground inside of tank berm.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Oil stained ground at load lines..**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Oil stained load lines. Seeping fittings.**



**Oil stained load lines. Seeping fittings.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Containers with fluids and build up.**



**Containers with fluids and build up.**

**BEEMAN OIL & GAS LLC  
JONES-66N87W 11NWSE  
Location # 316760**



**Weeds on access road.**