

Inspection Photos
location 467526
Inspection Date: 9/16/2022
All Photos taken by Kris Neidel



09.15.2022 15:50

Photo #1 cuttings bin. Some cuttings around the bin that need to be scraped up.



Inspection Photos
location 467526
Inspection Date: 9/16/2022
All Photos taken by Kris Neidel



Photo #2 black on the pad appears to be cuttings that have been driven into the pad.



Inspection Photos
location 467526
Inspection Date: 9/16/2022
All Photos taken by Kris Neidel



Photo #3 cuttings around the bin and pad.



Inspection Photos
location 467526
Inspection Date: 9/16/2022
All Photos taken by Kris Neidel



Photo #4 chemical spill on rig skid on south side of pad

Inspection Photos
location 467526
Inspection Date: 9/16/2022
All Photos taken by Kris Neidel



Photo #5 crews were installing subsurface flowlines at wellheads.

