

Final Reclamation and Stormwater Inspection

Date: 09/13/2022

Operator: H2E OPERATIONS LLC - 10498

Location ID: 438081

Inspection Document #: 696105425

Kit Carson County, CO

SWSE Section 22 T10S R45W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: H2E SCHAAL #3-4-22-10-45
Location ID: 438081



Photo 1. Photo taken from county road, facing north. Photo illustrates cattle guard remains at old access road entrance; fencing on perimeter of location remains. This material is now considered equipment/debris and needs to be removed.

Inspection Photos
Location Name: H2E SCHAAL #3-4-22-10-45
Location ID: 438081



Photo 2. Photo taken from southern portion of location facing north. Photo illustrates desirable vegetation has established; buffalo grass, sand drop seed, blue grama, etc was observed during this inspection. This location meets final reclamation rules and standards for revegetation.

Inspection Photos
Location Name: H2E SCHAAL #3-4-22-10-45
Location ID: 438081



Photo 3. Facing east, see comments in photo 2.

Inspection Photos
Location Name: H2E SCHAAL #3-4-22-10-45
Location ID: 438081



Photo 4. Facing south, see comments in photo 2.

Inspection Photos
Location Name: H2E SCHAAL #3-4-22-10-45
Location ID: 438081



Photo 5. Facing west, see comments in photo 2.

Inspection Photos
Location Name: H2E SCHAAL #3-4-22-10-45
Location ID: 438081



Photo 6. Reference area photo taken south and east of location, facing east. Photo illustrates reference area is predominantly buffalo grass and blue grama.