

Final Reclamation and Stormwater Inspection

Date: 09/13/2022

Operator: P O & G OPERATING LLC - 10634

Location ID: 324942

Inspection Document #: 696105426

Kit Carson County, CO

NENW Section 21 T10S R45W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BEESON #3-21
Location ID: 324942



Photo 1. Taken from northern portion of location, facing south. Photo illustrates location has not been reclaimed with presence of oil and gas equipment, annual weedy vegetation (e.g. kochia, russian thistle), road base/ gravel located throughout, pipe and rods, oily stained soils, and perimeter fencing observed.

Inspection Photos
Location Name: BEESON #3-21
Location ID: 324942



Photo 2. Taken from western portion, facing east. See comments in photo 1.

Inspection Photos
Location Name: BEESON #3-21
Location ID: 324942



Photo 3. Taken from southern portion, facing northeast. See comments in photo 1.

Inspection Photos
Location Name: BEESON #3-21
Location ID: 324942



Photo 4. Taken from southern portion, facing south. See comments in photo 1.

Inspection Photos
Location Name: BEESON #3-21
Location ID: 324942



Photo 5. Close up photo of gravel/cobble/road base on location.

Inspection Photos
Location Name: BEESON #3-21
Location ID: 324942



Photo 6. Taken from southern portion, facing north. See comments in photo 1.

Inspection Photos
Location Name: BEESON #3-21
Location ID: 324942



Photo 7. Taken from center/eastern portion, facing north. See comments photo 1.

Inspection Photos
Location Name: BEESON #3-21
Location ID: 324942



Photo 8. Close up photo of tank batteries with missing manhole covers and oily stained soils.



Photo 9. Close up photo of oily stained soil near tank batteries.