

Final Reclamation and Stormwater Inspection

Date: 09/13/2022

Operator: P O & G OPERATING LLC - 10634

Location ID: 324943

Inspection Document #: 696105427

Kit Carson County, CO

NWNW Section 21 T10S R45W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BEESON #4-21
Location ID: 324943



Photo 1. Taken from beginning of access road, facing west. Photo illustrates access road has not been reclaimed.

Inspection Photos
Location Name: BEESON #4-21
Location ID: 324943



Photo 2. Close up photo of gravel/cobble/road base on access road, illustrating the access road has not been reclaimed.

Inspection Photos
Location Name: BEESON #4-21
Location ID: 324943



Photo 3. Taken from middle portion of access road, facing south. See comments in photo 1.

Inspection Photos
Location Name: BEESON #4-21
Location ID: 324943



Photo 4. Taken west of location, facing east. Photo illustrates location has not been reclaimed with presence of annual weedy vegetation, russian thistle (outlined in red); bare soil resulting from non-uniform vegetation cover; and has not been recontoured or graded to reflect reference areas.

Inspection Photos
Location Name: BEESON #4-21
Location ID: 324943



Photo 5. Taken south of location, facing northeast. See comments in photo 4.

Inspection Photos
Location Name: BEESON #4-21
Location ID: 324943



Photo 6. Taken east of location, facing west. See comments in photo 4.

Inspection Photos
Location Name: BEESON #4-21
Location ID: 324943



Photo 7. Close up photo of location illustrating bare soil, weedy annual vegetation, and some debris left on site.

Inspection Photos
Location Name: BEESON #4-21
Location ID: 324943



Photo 8. Reference area photo taken southwest of location, facing southwest. Predominantly buffalo grass and sideoats grama.