

Inspection Photos

API: 071-08630

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08630 | Date: 9/16/2022

Inspection Photos



Photo 1. Facing southwest toward the access road. There was a white substance spilled on the ground at red arrow. This will need to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08630 | Date: 9/16/2022

Inspection Photos



Photo 2. Facing toward the wellsite. There are multiple areas of oil stained soils that need to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08630 | Date: 9/16/2022

Inspection Photos



Photo 3. There are oil stained soils at the wellhead that must be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08630 | Date: 9/16/2022

Inspection Photos



Photo 4. There are additional areas of spills that had occurred. All stained soils need to be cleaned up and properly disposed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08630 | Date: 9/16/2022

Inspection Photos



Photo 5. The well sign is posted at the meter shed.



Inspection Photos



Photo 6. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08630 | Date: 9/16/2022