

Inspection Photos
Location Name: Newton 1-4H
Location ID: 421003



Photo 1 – Sign at Entrance

Photo 2 – ECDS

Inspection Photos
Location Name: Newton 1-4H
Location ID: 421003



Photo 3 – Separator and Compressor

Photo 4 – Separator

Inspection Photos
Location Name: Newton 1-4H
Location ID: 421003



Colorado Oil and Gas Conservation Commission
40.78303, -104.20362, 4963.2ft, 172°
09/15/2022 12:34:02



Colorado Oil and Gas Conservation Commission
40.78295, -104.2036, 4959.7ft, 110°
09/15/2022 12:34:20

Photo 5 – Tank Battery

Photo 6 – Water Tank Labels

Inspection Photos
Location Name: Newton 1-4H
Location ID: 421003



Photo 7 – Tank Battery

Photo 8 – Unused Valves at Tanks

Inspection Photos
Location Name: Newton 1-4H
Location ID: 421003



Photo 9 – Pumping Unit




Photo 10 – Unmarked 1" Riser

Inspection Photos
Location Name: Newton 1-4H
Location ID: 421003



Photo 11 – Unused Valves and Rods




Photo 12 – Unmarked 1" Riser

Inspection Photos
Location Name: Newton 1-4H
Location ID: 421003



Photo 13 – Unused Stand and Wood Pallets

Photo 14 – Wellhead