

# Final Reclamation Inspection

September 13, 2022

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 317958

Inspection Document #: 697504178

Weld County, CO

NENE Section 26 T1N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: MOSER #1  
Location ID: 317958



**Photo 1.** Photo taken from the location, facing Southwest. Photo illustrates the location is not reflective of reference area crops and lacks the establishment of alfalfa.



Inspection Photos  
Location Name: MOSER #1  
Location ID: 317958



**Photo 2.** Reference photo taken from the location, facing West.



**Photo 3.** Photo taken from the location, facing Northeast. See comments under Photo 1.

Inspection Photos  
Location Name: MOSER #1  
Location ID: 317958



**Photo 4.** Photo taken from the location, facing North. Photo illustrates the access road which is being used by the surface owner for agricultural purposes.