

Final Reclamation Inspection

July 19th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 323266

Inspection Document #: 701900461

NESE Section 25 T4N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bowen 1
Location ID: 323266



Photo 1. 2021 aerial imagery of the well pad, access road and associated tank battery. Note: tank battery falls within a residential area.

Inspection Photos
Location Name: Bowen 1
Location ID:323266




Photo 2. Overview photo of the well pad, access road and reference area taken from a drone. Note: well pad disturbance and access road appear consistent with the adjacent crop reference area.

Inspection Photos
Location Name: Bowen 1
Location ID:323266



Photo 3. Overview photo of the tank battery taken at ground level from the eastern edge looking west.