

# Final Reclamation Inspection

July 19th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 327289

Inspection Document #: 701900463

SESE Section 28 T4N R66W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**


Department of Natural Resources

Inspection Photos  
Location Name: Lorenz 44-28  
Location ID: 327289



**Photo 1.** Overview photo of the well pad, access road and associated tank battery. Note: the tank battery now falls within the active PDC Hunt Federal production facility, location ID 442636.

Inspection Photos  
Location Name: Lorenz 44-28  
Location ID:327289



**Photo 2.** Overview photo of the well pad, access road and reference area taken with a drone. Note: well pad disturbance and access road appear consistent with the adjacent crop reference area.

Inspection Photos  
Location Name: Lorenz 44-28  
Location ID:327289



**Photo 3.** Ground photo taken from the eastern edge of the well facing west down the access road.

Inspection Photos  
Location Name: Lorenz 44-28  
Location ID:327289



**Photo 4.** Overview photo of the tank battery taken at ground level from the western edge facing east. Note: tank battery has an open remediation.

Inspection Photos  
Location Name: Lorenz 44-28  
Location ID:327289



**Photo 5.** Open remediation at tank battery. Spill remediation under document #200439420. Monitoring wells were observed on site during the inspection. Tank Battery status will remain in-process until remediation has closed and location can be re-inspected.