

Inspection Photos

API: 071-07767

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07767 | Date: 9/16/2022

Inspection Photos



Photo 1. Facing northeast toward the location which is recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2022

Inspection Photos



Photo 2. Facing toward the southeast portion of the location. This area of erosion needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2022

Inspection Photos



Photo 3. Facing west at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2022

Inspection Photos



Photo 4. Facing southeast toward the location which is recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07766 | Date: 9/16/2022