

Inspection Photos

API: 071-09295

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09295 | Date: 9/16/2022

Inspection Photos



Photo 1. Facing northwest along the access road. The road had been regraded to repair erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09295 | Date: 9/16/2022

Inspection Photos



Photo 2. Facing northwest along the access road. The road had been regraded to repair erosion. Ongoing maintenance will be needed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09295 | Date: 9/16/2022

Inspection Photos



Photo 3. Facing east along the access road toward the location. The road had been regraded to repair erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09295 | Date: 9/16/2022

Inspection Photos



Photo 4. Facing east toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09295 | Date: 9/16/2022