

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W /20SESW

Location ID: 335183



Photo #7726 From entrance to location.



Photo #7728 From entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W /20SESW

Location ID: 335183



Photo #7729 Loadline open ended.



Photo #7730 Undesirable plant species in tank containment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W /20SESW

Location ID: 335183



Photo #7731 Undesirable plant species in tank containment.



Photo #7732 Undesirable plant species in tank containment.