

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W /29SWNE

Location ID: 335298



Photo #7733 From entrance to location.



Photo #7734 From entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W /29SWNE

Location ID: 335298



Photo #7735 BMP's have not been implemented around stockpiled soils.



Photo #7736 Soils covering BMPs have not been implemented.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W /29SWNE

Location ID: 335298



Photo #7738 BMP's have not been implemented around stockpiled soils.



Photo #7739 BMP's have not been implemented around stockpiled soils.