

Inspection Photos

September 15, 2022

Operator: KP Kauffman Company Inc - #46290

Location ID: 324676

Location Name: Conoco Federal-69N78W /8SWSW

Inspection Document #: 702800703

Jackson County, CO

SWSW Section 8 T9N R78W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Conoco Federal-69N78W /8SWSW

Location ID: 324676



Photo 1. Photo taken from the center of the Location shows an overview of the former wellhead and tank battery area. Pad is flat, compacted and gravel remains. A cut slope remains to the west. Reclamation has not been performed.



Photo 2. Photo taken from the west shows the unreclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800703

Inspection Photos

Location Name: Conoco Federal-69N78W /8SWSW

Location ID: 324676



Photo 3. Photo taken from the west shows an overview of the equipment area remaining on Location. A gravel and concrete pad and riser equipment are present.



Photo 4. Photo shows the equipment remaining at the west of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800703

Inspection Photos

Location Name: Conoco Federal-69N78W /8SWSW

Location ID: 324676



Photo 5. Photo taken from the south of the Location shows trash/debris.



Photo 6. Photo taken from the south of the Location shows equipment remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800703

Inspection Photos

Location Name: Conoco Federal-69N78W /8SWSW

Location ID: 324676




Photo 7. Photos taken from the north of the Location show equipment remaining.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800703

Inspection Photos

Location Name: Conoco Federal-69N78W /8SWSW

Location ID: 324676



Photo 8. Photo taken from the north of the Location shows areas outside the former working pad area to the northeast appear to have been previously reclaimed and are vegetated with perennial grasses.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800703

Inspection Photos

Location Name: Conoco Federal-69N78W /8SWSW

Location ID: 324676



Photo 9. Photo taken from the southeast of the Location shows the site of a remediated 2005 spill. The area is vegetated, however desirable cover is not uniform. The tan vegetation is perennial grasses, the red vegetation is Russian thistle (annual, undesirable plant species/weed).



Photo 10. Photo shows a berm and pond feature at the terminus of the 2005 spill area. The purpose of this feature is unclear. Operator must reclaim this area or provide documentation from the surface owner that the feature is unrelated to the Location and/or spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800703

Inspection Photos

Location Name: Conoco Federal-69N78W /8SWSW

Location ID: 324676



Photo 11. Photo shows the area of a remediated 2005 spill to the southeast of the Location. Revegetation has failed in some areas. Photo shows erosion occurring in areas with bare ground and tumbling saltweed (annual, undesirable plant species/weed).



Photo 12. Refer to Photo 11 comment. Note also the power line in the background which must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800703

Inspection Photos
Location Name: Conoco Federal-69N78W /8SWSW
Location ID: 324676



Photo 13. Photo taken to the north of the Location shows reference area vegetation.