

Final Reclamation and Stormwater Inspection

Date: 09/14/2022

Operator: ENERGY QUEST II LLC - 10490

Location ID: 337062

Inspection Document #: 696105432

Yuma County, CO

SESE Section 3 T5S R44W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LIKE #3-16
Location ID: 337062



Photo 1. Taken from county road, facing west. Photo illustrates that access road has not been reclaimed and perimeter fencing is still installed (outlined in red); this is considered debris and needs to be disposed of properly.

Inspection Photos
Location Name: LIKE #3-16
Location ID: 337062



Photo 2. Facing west, see comments in photo 1.

Inspection Photos
Location Name: LIKE #3-16
Location ID: 337062



Photo 3. Access road facing west, see comments in photo 1.

Inspection Photos
Location Name: LIKE #3-16
Location ID: 337062



Photo 4. Close up photo showing access road has not been reclaimed with presence of rutting and annual weedy vegetation (predominantly russian thistle).

Inspection Photos
Location Name: LIKE #3-16
Location ID: 337062



Photo 5. Taken from southern portion of location, facing northwest. Photo illustrates that location has not been reclaimed. Non-uniform vegetation cover resulting in bare soil, annual weedy vegetation (russian thistle and kochia) observed throughout the location, and rill/gully erosion resulting from unstabilized soil.



Inspection Photos
Location Name: LIKE #3-16
Location ID: 337062



Photo 6. Facing north; degraded and/or improperly installed straw wattles outlined in red. These are considered debris and need to be disposed of properly.

Inspection Photos
Location Name: LIKE #3-16
Location ID: 337062



Photo 7. Facing east, see comments in photo 6.

Inspection Photos
Location Name: LIKE #3-16
Location ID: 337062



Photo 8. Close up photo of gully erosion on location.

Inspection Photos
Location Name: LIKE #3-16
Location ID: 337062



Photo 9. Taken from northern portion of location, facing south. Photo illustrates that location has not been reclaimed (outlined in red).