

# Final Reclamation and Stormwater Inspection

Date: 09/14/2022

Operator: ENERGY QUEST II LLC - 10490

Location ID: 337055

Inspection Document #: 696105435

Yuma County, CO

NWSE Section 3 T5S R44W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: LIKE #3-10  
Location ID: 337055



**Photo 1.** Taken from access road, facing northwest. Photo illustrates access road has not been reclaimed. Annual weedy vegetation (russian thistle) pictured.



Inspection Photos  
Location Name: LIKE #3-10  
Location ID: 337055



**Photo 2.** Facing north, see comments in photo 1.



Inspection Photos  
Location Name: LIKE #3-10  
Location ID: 337055



**Photo 3.** South of location, facing east, see comments in photo 1.



Inspection Photos  
Location Name: LIKE #3-10  
Location ID: 337055



**Photo 4.** Taken from location, facing north. Photo illustrates location has not been reclaimed. Bare soil resulting from non-uniform vegetation cover; annual weedy vegetation (e.g. russian thistle); perimeter fencing still remains and is now considered debris.



Inspection Photos  
Location Name: LIKE #3-10  
Location ID: 337055



**Photo 5.** Facing east, see comments in photo 4.



Inspection Photos  
Location Name: LIKE #3-10  
Location ID: 337055



**Photo 6.** Facing south, see comments in photo 4.



Inspection Photos  
Location Name: LIKE #3-10  
Location ID: 337055



**Photo 7.** Facing west; see comments in photo 4.



Inspection Photos  
Location Name: LIKE #3-10  
Location ID: 337055



**Photo 8.** Reference area photo taken north of location, facing north (predominantly buffalo grass).