

Final Reclamation and Stormwater Inspection

Date: 09/14/2022

Operator: ENERGY QUEST II LLC - 10490

Location ID: 337056

Inspection Document #: 696105436

Yuma County, CO

SWNE Section 3 T5S R44W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LIKE #3-7
Location ID: 337056



Photo 1. Taken from beginning of access road, southeast of location, facing north. Photo illustrates that the access road has not be contoured and regraded to reflect reference areas.

Inspection Photos
Location Name: LIKE #3-7
Location ID: 337056



Photo 2. Taken from southeast portion of location and access road, facing west. See comments in photo 1.

Inspection Photos
Location Name: LIKE #3-7
Location ID: 337056



Photo 3. Close up photo of straw wattle, which is now considered debris and needs to be removed, and field bindweed (CO List C Noxious Weed) outlined in red.

Inspection Photos
Location Name: LIKE #3-7
Location ID: 337056



Photo 4. Taken from center portion of location, facing north. Photo illustrates location has not been reclaimed with lack of uniform vegetation cover (e.g. bare soil) and areas that have not been contoured and regraded to reflect reference areas.

Inspection Photos
Location Name: LIKE #3-7
Location ID: 337056



Photo 5. Facing west, see comments in photo 4.

Inspection Photos
Location Name: LIKE #3-7
Location ID: 337056



Photo 6. Facing south, see comments in photo 4.