

Final Reclamation Inspection

August 2nd, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 333330

Inspection Document #: 701900512

SESW Section 24 T6N R66W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Seeley Lake 4
Location ID: 333330




Photo 1. 2021 aerial imagery of the well pad. Note: the tank battery highlighted in blue is associated with the Seeley Lake 5 well API #123-23657.

Inspection Photos
Location Name: Seeley Lake 4
Location ID: 333330



Photo 2. Overview photo the well pad and reference area taken from directly above the well disturbance using a drone. Note: well pad appears consistent with adjacent crop reference.

Inspection Photos
Location Name: Seeley Lake 4
Location ID: 333330



Photo 3. Overview photo of the well pad crop field taken at ground level from the western edge of the field facing east.