

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403154894

Date Received:

09/02/2022

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>.General</u>		<u>sjninspections@ikavenergy.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 702500321

Inspection Date: 08/22/2022

FIR Submit Date: 08/22/2022

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

**LOCATION - Location ID: 325501**

Location Name: SHOEMAKER-N35N8W Number: 34NWSE County: LA PLATA

Qtrqtr: NWSE Sec: 34 Twp: 35N Range: 8W Meridian: N

Latitude: 37.255727 Longitude: -107.728732

**FACILITY - API Number: 05-067-00 Facility ID: 214901**

Facility Name: SHOEMAKER Number: 01-34 1

Qtrqtr: NWSE Sec: 34 Twp: 35N Range: 8W Meridian: N

Latitude: 37.255727 Longitude: -107.728732

**CORRECTIVE ACTIONS:**

**1**  CA# 164015

Corrective Action: Remove debris or unused equipment per rule 606.

Date: 09/06/2022

Response: CA COMPLETED

Date of Completion: 08/30/2022

Operator Comment: Removed debris (PVC pipe) from location.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

CA from previous inspection Doc# 702500321 has been satisfactorily completed.

2  CA# 164016

Corrective Action: Repair/modify required BMPs per Rule 1002.f.(2)C

Date: 09/06/2022

Response: CA COMPLETED

Date of Completion: 08/30/2022

Operator Comment:

Replaced old wattles with new ones and reset existing wattles that were in good condition.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

CA from previous inspection Doc# 702500321 has been satisfactorily completed.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CAs completed. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: \_\_\_\_\_

Title: Permitting Specialist I

Date: 9/2/2022 8:44:29 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403154894	FIR RESOLUTION SUBMITTED
403154905	Shoemaker 01-34 1, CA Completion Photos

Total Attach: 2 Files