

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403173984

Date Received:

09/22/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10766

Name of Operator: ARKOMA OPERATIONS LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Price, Andrew

918-260-8324

aprice@arkomaops.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500439

Inspection Date: 09/13/2022

FIR Submit Date: 09/13/2022

FIR Status: _____

Inspected Operator Information:

Company Name: ARKOMA OPERATIONS LLC

Company Number: 10766

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

LOCATION - Location ID: 333414

Location Name: CRIGLER-MVRD UNIT-N33N8W Number: 21NENW County: LA PLATA

Qtrqtr: NENW Sec: 21 Twp: 33N Range: 8W Meridian: N

Latitude: 37.094120 Longitude: -107.726120

FACILITY - API Number: 05-067-00 Facility ID: 214076

Facility Name: CRIGLER-MVRD UNIT Number: 1

Qtrqtr: NENW Sec: 21 Twp: 33N Range: 8W Meridian: N

Latitude: 37.094120 Longitude: -107.726120

CORRECTIVE ACTIONS:

1 ☒ CA# 164539

Corrective Action: Calibrate gas metering equipment annually to comply with rule 430.d.(1).

Date: 10/14/2022

Response: CA COMPLETED

Date of Completion: 09/21/2022

Operator Comment: When creating our internal calibration schedule the Crigler-MVRD Unit #1 (05377) was confused with the Crigler MVRD Unit #1 (05335) and the same "last calibrated date" was used for both, resulting in the Crigler-MVRD Unit #1 not getting calibrated in 01/2022. Correct well was calibrated 9/21/22 and is scheduled to be done again in 09/23.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

CA from previous inspection Doc# 702500439 has been satisfactorily completed.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: _____

Title: Engineering Analyst

Date: 9/22/2022 7:42:40 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

403173984	FIR RESOLUTION SUBMITTED
403173991	Crigler-MVRD Unit 1 Remedial Report (702500439)

Total Attach: 2 Files