

Final Reclamation Inspection

August 7th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 323620

Inspection Document #: 701900566

SENW Section 5 T5N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Noffsinger 1
Location ID: 323620



Photo 1. 2021 aerial imagery of the well. Note: tank battery highlighted in blue has an open remediation and will remain in process until remediation has closed and disturbance can be re-inspected.

Inspection Photos
Location Name: Noffsinger 1
Location ID: 323620



Photo 2. Overview photo of the well pad and reference area taken from the southern edge facing north using a drone. Note: well pad appears consistent with adjacent crop reference area.