

# Inspection Photos

API: 071-09494

Operator: OGRIS OPERATING LLC

Inspection Date: 9/21/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09494 | Date: 9/21/2022

## Inspection Photos



**Photo 1.** Facing southwest toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09494 | Date: 9/21/2022



## Inspection Photos



**Photo 2.** The fence around the pit is not maintained. May need to consider more robust fencing around lined pits.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09494 | Date: 9/21/2022