

# Inspection Photos

API: 071-09113

Operator: OGRIS OPERATING LLC

Inspection Date: 9/21/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09113 | Date: 9/21/2022

## Inspection Photos



**Photo 1.** Facing south along the main access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09113 | Date: 9/21/2022

## Inspection Photos



**Photo 2.** Facing southwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09113 | Date: 9/21/2022

## Inspection Photos



**Photo 3.** Facing toward the fill slope which is stabilized with perennial vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09113 | Date: 9/21/2022