

# Inspection Photos

API: 071-09508

Operator: OGRIS OPERATING LLC

Inspection Date: 9/21/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09508 | Date: 9/21/2022

## Inspection Photos



**Photo 1.** Facing southeast along the access road which was recently graded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09508 | Date: 9/21/2022

## Inspection Photos



**Photo 2.** Facing southeast toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09508 | Date: 9/21/2022



## Inspection Photos



**Photo 3.** Facing toward the lined pit. The fence around the pit is maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09508 | Date: 9/21/2022