

Inspection Photos

API: 071-06435

Operator: OGRIS OPERATING LLC

Inspection Date: 9/21/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06435 | Date: 9/21/2022

Inspection Photos



Photo 1. Facing northwest along the reclaimed access road. The perennial vegetation is progressing along most reclaimed areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06435 | Date: 9/21/2022

Inspection Photos



Photo 2. Facing northwest along the reclaimed access road. This area of the road would benefit from additional hand seeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06435 | Date: 9/21/2022

Inspection Photos



Photo 3. Facing southeast along the reclaimed access road. This area of the road would benefit from additional hand seeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06435 | Date: 9/21/2022

Inspection Photos



Photo 4. Facing southeast along the reclaimed road. Noxious weeds appear to be controlled at this time.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06435 | Date: 9/21/2022