

# Inspection Photos

September 16, 2022

Operator: Gulf Exploration LLC - #10728

Location ID: 466705

Location Name: Eagle Hill 1-32 Pad

Inspection Document #: 702800728

Jackson County, CO

NWNE Section 32 T10N R78W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Eagle Hill 1-32 Pad  
Location ID: 466705



**Photo 1.** Photo shows the southern portion of the Location access road. The vegetation community is dominated by cheatgrass (List C Noxious Weed). Perennial grasses are subdominant.



**Photo 2.** Photo shows the northern portion of the Location access road. The vegetation community is dominated by tumbling saltweed (annual, undesirable plant species/weed). Perennial grasses are sparse.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800728

Inspection Photos  
Location Name: Eagle Hill 1-32 Pad  
Location ID: 466705



**Photo 3.** Photo taken from the location access road shows where water is beginning to undercut a wattle.



**Photo 4.** Refer to Photo 3 comment.

Inspection Photos  
Location Name: Eagle Hill 1-32 Pad  
Location ID: 466705



**Photo 5.** Photo taken from access road swale. Stormwater BMPs have been installed per good engineering practices. Photo also shows perennials (green plants) are well established on portions of the road and poorly established in other areas, where bare ground or cheatgrass (tan plants) dominate.



**Photo 6.** Refer to Photo 5 comment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800728

Inspection Photos  
Location Name: Eagle Hill 1-32 Pad  
Location ID: 466705



**Photo 7.** Photo taken from the east shows an overview of the reclaimed Location.



**Photo 8.** Photo taken from the northwest shows an overview of the reclaimed Location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800728

Inspection Photos  
Location Name: Eagle Hill 1-32 Pad  
Location ID: 466705



**Photo 9.** Photo taken from the northwest shows the start of the disturbed area vegetation monitoring transect.



**Photo 10.** Photo taken from the northwest shows the ground surface at the start of the disturbed area vegetation monitoring transect.

Inspection Photos  
Location Name: Eagle Hill 1-32 Pad  
Location ID: 466705



**Photo 11.** Photo taken from the north shows the end of the disturbed area vegetation monitoring transect.




**Photo 12.** Photo taken from the north shows the ground surface at the end of the disturbed area vegetation monitoring transect.

Inspection Photos  
Location Name: Eagle Hill 1-32 Pad  
Location ID: 466705



**Photo 13.** Photo taken to the north of the Location shows the start of the reference area vegetation monitoring transect.



**Photo 14.** Photo taken to the north of the Location shows the ground surface at the start of the reference area vegetation monitoring transect.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800728

Inspection Photos  
Location Name: Eagle Hill 1-32 Pad  
Location ID: 466705



**Photo 15.** Photo taken to the north of the Location shows the end of the reference area vegetation monitoring transect.



**Photo 16.** Photo taken to the north of the Location shows the ground surface at the end of the reference area vegetation monitoring transect.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800728