

# Inspection Photos and Issue Report

9/22/2022

Operator: CAERUS PICEANCE LLC - 10456

Location #445862

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #445862



**Photo 1:** Photos taken from the sediment trap on the north end of the Location. Though work to maintain sediment trap has been conducted, work has not been conducted in accordance with good engineering practices; geotextile lining has not been installed at the inlets/outlets with the rip-rap material.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #445862



September 22, 2022



September 22, 2022

**Photo 2:** Photos taken from the sediment trap on the north end of the Location. Though work to maintain sediment trap has been conducted, work has not been conducted in accordance with good engineering practices; geotextile lining has not been installed at the inlets/outlets with the rip-rap material.

