

Inspection Photos and Issue Report

9/22/2022

Operator: CAERUS PICEANCE LLC - 10456

Location #441653

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #441653



Photo 2: Photo taken from east end of the working pad. Photo shows Operator has installed a berm to prevent stormwater runoff from discharge to the eastern interim areas of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #441653



Photo 2: Photos taken from the eastern interim areas of the Location. Photo shows gully erosion has been repaired. BMPs to stabilize the soils on the slope are missing or insufficient.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #441653



Photo 3: Photos show wildlife protection BMPs have been implemented at tanks.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #441653



Photo 4: Photo shows trash/debris has been removed from the southern end of the Location.