

# Inspection Photos

September 15, 2022

Operator: Bonanza Creek Energy Operating Company  
LLC - #8960

Location ID: 324681

Location Name: Federal-69N78W /27SWSE

Inspection Document #: 702800719

Jackson County, CO

SWSE Section 27 T9N R78W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Federal-69N78W /27SWSE  
Location ID: 324681



**Photo 1.** Photo shows an overview of the Location.



**Photo 2.** Photo shows an overview of the Location.

Inspection Photos  
Location Name: Federal-69N78W /27SWSE  
Location ID: 324681



**Photo 3.** Photo shows the direct Location access road to the south.



**Photo 4.** Photo shows the access road from county road 12E to the southeast of the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800719

Inspection Photos  
Location Name: Federal-69N78W /27SWSE  
Location ID: 324681



**Photo 5.** Photo shows a wire coming out the ground at the west of the Location.

## Inspection Photos

Location Name: Federal-69N78W /27SWSE

Location ID: 324681



**Photo 6.** Photo shows erosion occurring at the southeast of the Location.



**Photo 7.** Photo shows erosion occurring at the north of the Location.



**COLORADO**

Oil & Gas Conservation  
Commission


Department of Natural Resources

Inspection Number: 702800719

## Inspection Photos

Location Name: Federal-69N78W /27SWSE

Location ID: 324681



**Photo 8.** Photo shows erosion occurring at the center of the Location.



**Photo 9.** Photo shows erosion occurring at the west of the Location.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800719

Inspection Photos  
Location Name: Federal-69N78W /27SWSE  
Location ID: 324681



**Photo 10.** Photo shows the plant community on Location is dominated by seeded perennial grasses.



**Photo 11.** Refer to Photo 10 comment.

Inspection Photos  
Location Name: Federal-69N78W /27SWSE  
Location ID: 324681



9/15/22  
+40.713116,-106.132575  
179° S

**Photo 12.** Photo taken to the south of the Location shows reference area vegetation.