

Inspection Photos

September 16, 2022

Operator: KP Kauffman Company Inc - #46290

Location ID: 438317

Location Name: SMU /22-6H

Inspection Document #: 702800721

Jackson County, CO

SWSW Section 22 T9N R78W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SMU /22-6H
Location ID: 438317



Photo 1. Photo taken to the east shows an overview of the southern portion of the reclaimed location.



Photo 2. Photo taken to the east shows an overview of the northern portion of the reclaimed location.

Inspection Photos
Location Name: SMU /22-6H
Location ID: 438317



Photo 3. Photo shows the vegetation community of the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800721

Inspection Photos
Location Name: SMU /22-6H
Location ID: 438317



Photo 4. Photo shows the vegetation community consists of a variety of native perennial grasses, shrubs and forbs.



Photo 5. Photo shows a close up of the vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800721

Inspection Photos
Location Name: SMU /22-6H
Location ID: 438317



Photo 6. Photo taken from the south of the Location shows the transition from the reclaimed location (left) to the reference area (right).



Inspection Photos
Location Name: SMU /22-6H
Location ID: 438317



Photo 7. Photo taken to the south of the Location shows reference area vegetation.

