

Inspection Photos

September 16, 2022

Operator: Bonanza Creek Energy Operating Company
LLC - #8960

Location ID: 324686

Location Name: Federal-69N78W /27NWSE

Inspection Document #: 702800726

Jackson County, CO

NWSE Section 27 T9N R78W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Federal-69N78W /27NWSE
Location ID: 324686



Photo 1. Photo shows the start of the Location access road. The road is not reclaimed; it is crowned, compacted and graveled. Vehicles appear to be utilizing it. The green vegetation in the center of the road is Canada thistle (CO List B Noxious).



Photo 2. Photo shows the Location access road as it leaves the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800726

Inspection Photos
Location Name: Federal-69N78W /27NWSE
Location ID: 324686



Photo 3. Photo taken from the northwest shows an overview of the Location and the vegetation.



Photo 4. Photo taken from the south shows an overview of the Location and the vegetation.

Inspection Photos
Location Name: Federal-69N78W /27NWSE
Location ID: 324686



Photo 5. Photo shows an anchor remaining at the northeast of the Location.



Photo 6. Photo shows what appears to be a locator wire remaining to the east of the Location.

Inspection Photos
Location Name: Federal-69N78W /27NWSE
Location ID: 324686



Photo 7. Photo shows a gully at the southeast of the Location resulting in onsite and offsite degradation.



Photo 8. Photo shows the where runoff from the Location is concentrating to form the gully pictured in Photo 7.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800726

Inspection Photos
Location Name: Federal-69N78W /27NWSE
Location ID: 324686



Photo 9. Photo taken to the north of the Location shows reference area vegetation.