

Construction and Stormwater Inspection

Date: 09/13/2022

Operator: EXTRACTION OIL AND GAS INC - 10459

Location ID: 449925

Inspection Document #: 696105470

Adams County, CO

SWSE Section 25 T1S R66W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ALMA 1S-66-2524 PAD
Location ID: 449925



Photo 1. Taken from beginning of access road, facing northwest. Annual weedy vegetation observed along access road; russian thistle outlined in red.

Inspection Photos
Location Name: ALMA 1S-66-2524 PAD
Location ID: 449925



Photo 2. Taken from southern portion, facing west. See comments in photo 1.

Inspection Photos
Location Name: ALMA 1S-66-2524 PAD
Location ID: 449925



Photo 3. Taken from southwest corner, facing southwest. See comments in photo 1.

Inspection Photos
Location Name: ALMA 1S-66-2524 PAD
Location ID: 449925



Photo 4. Taken from southwest corner, facing north. See comments in photo 1.

Inspection Photos
Location Name: ALMA 1S-66-2524 PAD
Location ID: 449925



Photo 5. Taken from southeast corner, facing east. Photo illustrates debris in ditch; this debris needs to be properly disposed.