



# Final Reclamation Inspection Form

Site: Ma-State #3  
 Date: 07/11/2022  
 Conditions: 64F overcast

Inspector: Peter Abrahamson

Land Use: Pasture  
 If Crop: \_\_\_\_\_  
 If other land use: \_\_\_\_\_

Access Road in Use: Yes  
 If yes, in use by: WFE  
 Located on active pad? Yes  
 Located in interim rec of active pad? Yes

TB inspected: Yes TB status: In Use

TB name and/or #: Ma-State TB-Well

	Present (Y/N)	Notes
Debris or Trash on Site	No	
Equipment on Site (culverts, pipes, etc.)	Yes	Pumpjack, Separator, Tank Battery, Vertical Separator, ECD & Flare
Livestock Grazing/Disturbances	No	
Vehicle Disturbances	No	
Wildlife Disturbances	No	
Seed Germination	Yes	
Plants Vigorous	Yes	
Uniform growth (height and density)	No	
Undesirable Species (non-noxious weeds)	Yes	
Noxious Weeds	No	
Stormwater Issues (erosion)	No	
Subsidence (depressions, sinking)	No	
Site Re-contoured Properly	Yes	
Road Re-contoured Properly	NA	
Road base/gravel on site (road or pad)	No	
Compaction (On-Site)	NA	
Compaction (Off-Site)	NA	
Reclamation area fenced	No	

Plants Observed	On Site	Off Site	Desirable
Prairie Sunflower	Yes	Yes	Yes
Wavyleaf Thistle	Yes	Yes	Yes
Purple Three-Awn	Yes	Yes	Yes
Blue Grama	Yes	Yes	Yes
White Goosefoot	Yes	Yes	Yes
Western Wheat Grass	Yes	Yes	Yes
White Prickly Poppy	Yes	Yes	Yes
Hairy False Goldenaster	Yes	Yes	Yes
Slender Russian Thistle	Yes	Yes	No
Summer Cypress	Yes	Yes	No
Field Bindweed	Yes	Yes	No
Buffalo Grass	Yes	Yes	Yes

Recommendations:	
Seeding	Yes
Weed Control	Yes
Erosion Control	No
Compaction Alleviation	No
Other:	

Other Comments/Observations: Recommend reseeding bare areas, Gravel stockpile on pad, oil stains along Separator berms

Recommend for Final Form 4? No



## PHOTOGRAPHIC LOG



**Photograph 1:** North facing photograph.



**Photograph 2:** East facing photograph.



**Photograph 3:** South facing photograph.



**Photograph 4:** West facing photograph.

PHOTOGRAPHIC LOG



Photograph 5: Overview photograph.