

Inspection Photos
Location Name: Pevler 14-22
Location ID: 410064



Photo 1 – Cut and Capped



Photo 2 – Wellsite

Inspection Photos
Location Name: Pevler 14-22
Location ID: 410064



**Photo 3 – Pumping Unit – 90 days from Plug date to remove
Surface Equipment is Approaching at 10.08.2022**